


Experimental Research at the Asian Institute of Technology 1990s


Some Research Examples

- Constant Rate of Strain Consolidometers
- Piezoprobes
- Shearing Mode of Vane
- Anisotropic Study

Constant Rate of Strain Consolidometer




a) CRS Consolidometer for Radial Drainage




b) CRS Consolidometer for Vertical Drainage

Pore Water Pressure Distribution under Radial Drainage Condition




a) Locations of pore water pressure measurement




b) Excess pore pressure ratio versus radius


CRS under Radial Flow Condition




Determination of Preconsolidation Pressure from Pore Pressure Ratio




Mini-Piezoprobe (Dissipation Test)




Dissipation Curves




PVD Embankment – Final Settlement Prediction




c_h versus Stress Range




Vane Shear Mode




Different Planes of Shearing




Stress-Displacement & Stress Paths SHANSEP Technique




Anisotropy & SHANSEP Parameters




Consolidated Laboratory Vane




True Triaxial –Flexible Boundaries





Stress Systems





Simulation of Pressuremeter Mode





True Triaxial vs Conventional Triaxial



Pressuremeter Plane Mode




Pressuremeter Simulation by FEM




**Some Testing Problems
Encountered**




Split Spoon Sampler



Shelby Tube



Vane



Sieve



Consolidation



Floating Ring Consolidometer

Electrostatic design eliminates friction between soil




Poor
Top
Cap




Proper
Top
Cap

Shear Box




Poor Force
Alignment



Proper Force
Alignment

Loading Frame



Some Interesting Geotechnical Works in Thailand



Ground Subsidence







**Unsuccessful Works – Prefabricated Vertical
Drains (1995)**



Unsuccessful Works – Prefabricated Vertical Drains (1995)



Unsuccessful Works – Soil Cement Columns (2007)

















Possible Failure Mechanism



Possible Causes




- 2 Stages
 - **Horizontal Cracks** due to high tensile wave when pile is in loose sand
 - **Pile Expansion** due to pressure buildup internally
- Pile Expansion
 - **High Energy Input** in loose sand with high water table resulted in high penetration
 - **High penetration/blow** gives rise to high water pressure buildup
 - **Water pressure** causes expansion of pile



Limit of Internal Pressure




- $D = 600 \text{ mm}$, $t = 100 \text{ mm}$, $d_i = 400 \text{ mm}$
- $f_c = 500 \text{ ksc}$, $f_t = 50 \text{ ksc}$



Remedial Measures




- Fill Inner Hole with Rebars and Concrete to improve Long Term Durability




Pile Tip Modification



- CCTV Inspection after Piling
- Plug partially with concrete



Standard Shoe



Modified Closed End

Augering and Lower Energy Input

