



coffey  **geotechnics**
SPECIALISTS MANAGING THE EARTH

BLUE MOUNTAINS CUTTINGS

Geotechnical Hazard Assessment



Cutting Details

- 1.5km long
- Maximum 65m high
- Series of cuts, steeply sloping natural slopes and benches
- Hawkesbury Sandstone
- Over 90 years old



Background


- Rock Fall from lower cut - blocked Up track
- Noticed by driver on Down track.
- 1 tonne rock could not be moved from track by driver
- Area previously assessed from **track level** by geotechnical engineer and no hazard identified




L 300 kg

Rock Fall Scarp

This is what the cut
looked like in about
1920




This is what the cut
looks like now




Investigations

- Hazard Assessment using rope access methods
- High resolution photographs taken from helicopter to produce photomosaics to present hazard locations for remedial works



16 photomosaics covering Up Main





Rock Fall while on site

- While assessments being carried out
- During rainfall



Rock shattered on impact
with fragments ending up
on rail corridor

What is causing these hazards?

- Age of the cuts
- Weathering of rock – significant onion skin weathering noted
- Vegetation – root jacking
- Drought – sending roots deeper and swelling after rainfall events



Rock falls caused by
root jacking near crest


Joint Slabs on faces

2 m

Weathering
along joints


Undercutting

- Easily loosened using a crowbar
- Such a fall could occur naturally due to weathering or root action
- Falls from lower cuts less likely to shatter – more likely to block track



Results

- Over 400 hazards identified
- 488 locations for rock bolts recommended
- Produced clear photomosaics showing hazards and planned remedial works.
- High risk hazards prioritised for treatment by scaling and rock bolting.



Extensive
damage to
overhead wiring
stanchion during
scaling

Extensive damage to
wiring trough

