

NICOLL HIGHWAY COLLAPSE



Courtesy: N.Prebaharan

Introduction

- ❖ On 20th April 2004 (3:30 pm) a 30m deep excavation in marine clay adjacent to Nicoll Highway (in Singapore) collapsed, resulting in the tragic loss of four lives.
- ❖ A Committee of Inquiry (CoI) was set up to ascertain the cause and circumstances of the incident.
- ❖ Evidence was given by 173 witnesses of fact and 20 experts.
- ❖ The Committee found out two main reasons for the failure:
 - ❖ Wrong design of the connection between the struts and walers
 - ❖ Wrong computer analysis used for the design of the retaining system
- ❖ Lessons learnt and the follow up actions taken will be discussed in this presentation.

Location



Location



Three Days Before the Collapse





TSA Shaft (35 m dia & 33 m deep)



After Collapse.....



Problems with the curved alignment




Deformation of mesh just before collapse, 3-D FEM

3-D FEM model indicated that some joints between the wall panels would open up, if the walers are not continuous

Survey of collapse Site

(Diaphragm wall panels moved independently to each other)


Strutting System Used (discontinuous walers)




More Pictures on the failure




Geological Section



Reclamation Stages




Undrained Shear Strength of Marine Clay




Construction Sequence

Installation of Rigid Foam Wall




Constructing Tunnel Bore and Backfilling



What were new in this Project?

- ❖ Deepest excavation in soft clay (~33 m)
- ❖ Temporary diaphragm wall (0.8 m thk) was used
 - ❖ Eliminate NSF on the piles & the tunnel box
 - ❖ Early starting of wall installation
- ❖ Deepest jet grouting –QC issues
 - ❖ Designed as a structural member/as a soil improved layer
- ❖ Sacrificial jet grout layer
- ❖ 2-D FEM model (Plaxis) used for the first time

Sacrificial Jet Grout Layer



What design shear strength should be used for the sacrificial layer?

-- Range of values



Was the jet grout layers contributed to the failure?

The jet grout layers were not considered as the main cause for the failure

This is because


- ❖ of the reported good quality ‘sacrificial’ jet grout layer; and
- ❖ there were not sufficient evidence to suggest any defects in the bottom jet grout layer

Strut Load




The strut load measurements showed that, on the day of the collapse, load was being transferred from the 9th to the 8th level of struts.

Observed Sway Failure of the Waling




(picture was taken a few hours before the collapse)

Details of Strut-Waler Connections



(a) Plate stiffener



(b) C-Channel stiffener


Failure is mainly due to the in-plane buckling of the plate and/or web with little or no side sway of the waler flange

C-channel stiffener and web to sway and failure can occur in a sudden manner with drastic reduction in capacity.

More sensitive to the effective length used in calculating the web buckling capacity

Typical Failure Modes Observed In Laboratory Physical Tests


Front View



Waler


Plate stiffener

Side View



In-plane buckling

(a) Plate stiffener (non-sway)





Sway failure

C-channel stiffener



(b) C-channel stiffener (brittle-sway)


Wall Deflection



Radius of curvature ~ 200 m

Hinge would have formed by 5 April


Wall Deflection—Trend Plot (Max. Displ. Vs Time) and Back analyses




Some Key Questions

- ❖ Why the excavation was not stopped?
- ❖ When should have stopped the excavation?
- ❖ Who should have stopped (PM, PE, QP or the BCA) ?
- ❖ If stopped
 - ❖ What next, i.e., what type of remedial action to go for?
 - ❖ What are the implications?


Modeling Undrained condition using M-C Model and Effective Stress Parameters—Why it is wrong for soft clays?



Undrained Shear Strength of Marine Clay



Plastic Hinges & Progressive Failure



Tension Crack in the Cricket Field



Major Causes of Collapse—A Summary

- ❖ **Errors in the design of the strut/waling connection resulted in this connection having about one half of the required capacity**
 - ❖ **This happened because of the substitution of ‘C’ channel for plate stiffeners in the waling**
- ❖ **Use of effective stress parameters + Mohr-Coulomb failure + ‘undrained’ analysis, to model soft marine clay in PLAXIS**
 - ❖ **This led to the underestimation of moments and movements of wall by a factor of about 2.**

Some Other Contributory Causes

- ❖ Diaphragm walls installed short of 3m design penetration in Old Alluvium – in one case by only 0.6m**
- ❖ Monitoring and monitoring review had been inadequate in quality**
- ❖ Backanalyses incorrectly carried out**

Lessons Learnt

❖ Design

- ❖ Effective stress parameters + Mohr-Coulomb FEM model should not be used to model undrained condition in soft clays
- ❖ Design of strut-waler connection is very important
 - ❖ Design should be done jointly by experienced geotechnical & structural engineers
 - ❖ Design should be checked by an independent design checker

Lessons Learnt

- ❖ The following would enhance the robustness of Temporary Earth Retaining System
 - ❖ Capping beams for the temporary walls
 - ❖ Continuous walers (especially in a curved alignment)
 - ❖ Concrete packing of the waler at the strut location
 - ❖ Effective lateral restraints of struts
- ❖ Adequate wall penetration into competent soil strata.
 - ❖ Closely spaced boreholes/CPTs

Lessons Learnt

❖ Monitoring

- ❖ The monitoring should be carried out & reviewed by experienced specialist
- ❖ Agreed monitoring frequency should be strictly adhered to
- ❖ Damaged instruments should be replaced immediately

Lessons Learnt

❖ Site Supervision

- ❖ Site personal should be properly briefed and trained
- ❖ The job description must match the appointee's background and experiences
- ❖ The project manager should have adequate relevant design and construction knowledge

Follow-Up Actions

- ❖ Independent checks for temporary works required
- ❖ No reduced FOS for temporary works (previously allowed under Singapore codes)
- ❖ Risk Assessments & Risk Registers now have to be more rigorous
- ❖ Instrumentation being installed and read by independent consultant for latest LTA works
- ❖ PE (Temporary Excavations and Retaining Systems) introduced