

Geophysics Case Studies: Slope Investigations



Prof. Bob Whiteley
Senior Principal


Unexpected slope & embankment collapses can have catastrophic consequences



Case studies

- **Deep road cut- New England Hwy.**
- **Slopes adjacent to rivers - Thailand**
- **Buried boulder location – Malaysia**
- **Mapping lithologies & buried hazards with ERI**
- **Seismic Imaging of hazardous slopes LHD**
- **Shear zone mapping for new road tunnel - Malaysia**



CREEP



FLOW

SLUMP

UNSTABLE MASSES



Key issues for geophysics

- **Depth and lateral extent of unstable mass**
- **Location and shape of base**
- **Buried objects e.g. boulders**
- **Groundwater conditions**
- **Possible surrounding unstable material**

UNSTABLE MASS PARAMETER INCREASING	SEISMIC VELOCITY	ELECTRICAL RESISTIVITY
Depth	↑	↑
Weathering (clay content)	↓	↓
Discontinuity frequency	↓	↓
Strength	↑	↑
Residual Stress	↑	↑
Saturation	↑	↓
Groundwater salinity	↔	↓



Increases




Decreases




No Change

Seismic Refraction


Seismic refraction




Seismograms



Travel time curve




Interpretation




Figures = Seismic velocities


Borehole Seismic



ELECTRICAL RESISTIVITY IMAGING







Seismic Refraction Profile



**Murrurrundi
Gap, NSW
road cut**









Project	Kwae Noi Dam Site Thailand
Nature of Instability	Slump failure right abutment
Task	Define unstable rock mass
Geophysical Technology	Seismic refraction



Seismic refraction data




Initial interpretation




Re-interpretation

Visual
Interactive
Ray
Tracing


FIRST ARRIVAL SEISMIC TRAVEL TIMES




SEISMIC RAYPATHS



FINAL INTERPRETED SECTION




Project	Road cutting Penang
Nature of Instability	Landslip in weathered granite
Task	Locate buried boulders
Geophysical Technology	Electrical resistivity






APPARENT RESISTIVITY PSEDOSECTION LINE S8




Apparent
Resistivity
(ohmm)


Interpreted
regions of
boulder
concentration
or shallow rock




**APPARENT RESISTIVITY CONTOUR PLAN
EFFECTIVE DEPTH 2.1m (n=1)**




**APPARENT RESISTIVITY CONTOUR PLAN
EFFECTIVE DEPTH 4.8m (n=3)**




APPARENT RESISTIVITY CONTOUR PLAN EFFECTIVE DEPTH 7.4m (n=5)






Lithological & soils mapping with Electrical Resistivity Imaging

Karst Features/Voids



ERI in highly variable conditions

Fracture Zones





**Site
location**



Some Historical - rock falls



1987-GD1



2001-GD3



2004-GD4



2004-GD2

Some Historical - Debris Flows



Circa 1880-GD3



1950-GD1- looking south



1950-GD2



1988-GD1

Debris flows from Bulgo
Slope up to 5000m³

Boulders on slope

Cliff collapse-Bulgo
Sandstone up to
1000m³

Rock falls 20-150 m³

Debris flows from Stanwell
Park Claystone Slope up
to 3000m³

Slab failure
Scarborough
Sandstone
~2000 m³

Rock falls to
20 m³ from
Scarborough
and Otford
sandstone

1300

1350

1400

1450


1250

Northern
Abutment

Large embankment
failure below road

P1
Shallow
embankment
failures


P2





borehole


Seismic
profile



Seismic Layer	P-wave velocity (km/s)	Thickness range (m)	Simplified borehole log
1	0.4-0.7	1-12	Silty sand (fill & colluvium)
2	0.8-2.5	6-23	EW to HW sandstone, conglomerate, sandy clay, some boulders
3	2.6-3.7	-	SW to F siltstone/sandstone with coal seams

Borehole Seismic Imaging Profiles

New Highway Construction







LEGEND

- BOREHOLE BHC 23
- LINE 1 SEISMIC PROFILE
- LINE 1 RESISTIVITY PROFILE

Elevated roadway under construction





LEGEND

- FILL/COLLUVIUM
- EW/HW SILTSTONE/SANDSTONE
- SW/F SILTSTONE/SANDSTONE
- INTERPRETED ROCK LEVEL (SW/F SILTSTONE/SANDSTONE)
- POSSIBLE FAULT

Coffey Geosciences Pty Ltd

ABN 57 056 335 516
ACN 056 335 516

Geotechnical | Resources | Environmental | Technical | Project Management

Drawn CC

Approved RJW

Date 6/01/04

LAWRENCE HARGRAVES DRIVE ALLIANCE
AREA GD4 NORTHERN AMPHITHEATRE
GEOPHYSICAL STUDY
SEISMIC IMAGES

FIGURE 2



Lawrence Hargrave Drive


Genting Malaysia: The Old Karak Road Tunnel



New Karak Road Tunnel

- **790 m of 8.4 m high & 11.4 m wide tunnel, 20 shafts in granite at 20 to 70 m depth**
- **Geotechnical and seismic investigations 1994 from limited drilling sites**
- **Construction by roadheaders 1995 - 97**

COFFEY GEOPHYSICS
Interpreted Seismic Tomographic Section
Tunnel Project, Malaysia





The shear zone exposed

