



Figure 4 Slope slide disaster photos at mileage 59.1k




Figure 5 Slope slide disaster photos at mileage 71.1k




Figure 6 Geological plan and profile at mileage 37.5k